

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

L95
ESE
1/8-1/4
0.180 mi.
953 ft.

2831 W. 8TH ST
2831 WEST 8TH STREET
BROOKLYN, NY

NY LTANKS
NY Spills

S104285115
N/A

Site 2 of 2 in cluster L

Relative:
Higher

Actual:
1 ft.

LTANKS:

Name: 2831 W. 8TH ST
Address: 2831 WEST 8TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9411963 / 2003-03-17
Facility ID: 9411963
Site ID: 310827
Spill Date: 1994-12-07
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 1991-12-07
CID: Not reported
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1995-01-24
Spill Record Last Update: 2013-05-08
Spiller Name: Not reported
Spiller Company: ADAM PIEL-OWNER
Spiller Address: 188 MOANHAN AVE
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 242483
DEC Memo: "05/08/13-Hiralkumar Patel. the subject spill was closed by Spills on 03/17/2003. received email from Jill Haimson (at 10:12 AM on 05/07/13) from Preferred Environmental including limited phase II report. Preferred installed total of 17 borings in area of former tanks and dispenser islands. groundwater was found at varying depths of 4 and 5 ft bg. during investigation, minor VOC contamination noted in groundwater sample. Ms. Haimson inquired if a new spill number needed. groundwater analyticals:
-----GW-1-----GW-5
1,2,4,5-Tetramethylbenzene-----100-----14
1,2,4-Trimethylbenzene-----22 1,3,5-Trimethylbenzene-----8
n-Butylbenzene-----13 sec-Butylbenzene-----9
discussed with DEC Austin. based on available information, no further investigation/remediation needed. 2:23 PM:- sent email to Jill and informed her that no further investigation/remediation needed. email copied to Bill at Preferred."

Remarks: "U/G PIPPING APPEARS TO HAV ELEAKED - DISCOVERED IN TANK PULL."

All Materials:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Site ID: 310827
Operable Unit ID: 1005597
Operable Unit: 01
Material ID: 374297
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: MANHOLE 62303
Address: 2831 WEST 8TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9911388 / 2002-03-28
Facility ID: 9911388
Facility Type: ER
DER Facility ID: 242483
Site ID: 233317
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1999-12-29
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1999-12-29
CID: 211
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-12-29
Spill Record Last Update: 2002-03-28
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: MARK SCHLAGEL
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "
Remarks: "1 PINT OF UNKNOWN OIL IN MANHOLE ON 100 GALS WATER - CLEAN UP PENDING LAB RESULTS - CON ED 129429"

All Materials:

Site ID: 233317
Operable Unit ID: 1090089
Operable Unit: 01
Material ID: 296848
Material Code: 0066A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: 2831 WEST 8TH STREET
Address: 2831 WEST 8TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9509494 / 2008-08-08
Facility ID: 9509494
Facility Type: ER
DER Facility ID: 242483
Site ID: 299761
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 1995-11-01
Investigator: hrpatel
Referred To: Not reported
Reported to Dept: 1995-11-01
CID: 266
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-11-01
Spill Record Last Update: 2008-08-08
Spiller Name: LENNY
Spiller Company: Not reported
Spiller Address: 2831 WEST 8TH STREET
Spiller Company: 001
Contact Name: LENNY
DEC Memo: "3/24/06 Diaz - Next steps-additional followup required. Spill transferred back to Region 2 3/10/08 - Austin - Spill assigned to Patel for followup - end 08/08/08-Hiralkumar Patel. went to site. its an abandoned open lot, with one single story office in corner. no contact info. case closed."

Remarks: "CALLER WAS CHANGING VENT AND PREPARING TO TEST SYSTEMS. FOUND SOME CONTAMINATED SOIL & A LEAK IN TANK. NOT A LOT OF SOIL. TANK PUMPED OUT & TO BE REMOVED. FURTHER EXCAVATION TO TAKE PLACE. TANK TO BE REPAIRED OR REPLACED AS NEEDED."

All Materials:
Site ID: 299761
Operable Unit ID: 1020050
Operable Unit: 01
Material ID: 360450
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported